

Inspection Report

Report No.: XYSJ-140704
Supplier : XY-GLOBAL

Inspection Date: 1st Aug, 2014
Inspector: Leo

Inspection only for: PO : XYSJ-140704 Item No. XY11KA002	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA002	26000PCS	5% inspection	0pcs	No failure	26000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



Item	Spec	Unit	Value	Unit	Value	Unit	Value	Unit	Value
1	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
2	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
3	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
4	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
5	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
6	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
7	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
8	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
9	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
10	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
11	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
12	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
13	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
14	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
15	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
16	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
17	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
18	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
19	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
20	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
21	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
22	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
23	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
24	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
25	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
26	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
27	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
28	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
29	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
30	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
31	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
32	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
33	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
34	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
35	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
36	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
37	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
38	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
39	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
40	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
41	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
42	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
43	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
44	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
45	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
46	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
47	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
48	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
49	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
50	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
51	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
52	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
53	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
54	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
55	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
56	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
57	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
58	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
59	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
60	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
61	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
62	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
63	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
64	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
65	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
66	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
67	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
68	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
69	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
70	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
71	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
72	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
73	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
74	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
75	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
76	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
77	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
78	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
79	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
80	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
81	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
82	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
83	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
84	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
85	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
86	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
87	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
88	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
89	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
90	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
91	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
92	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
93	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
94	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
95	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
96	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
97	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
98	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
99	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00
100	XY11KA002	mm	10.00	mm	10.00	mm	10.00	mm	10.00

5. Product:

6. The test report

[illegible]

Safety is our serious job for our worker and engineer team

