

Inspection Report

Report No.: XYBA-141117

Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYBA-141117 Item No. XY21ZC037	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC037	6000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS
XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS
XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS
XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS
XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS
XY21ZC037									
Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Lot No.	141117	141117	141117	141117	141117	141117	141117	141117	141117
Inspection Date	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014	19/12/2014
Inspector	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO	LEO
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description									
Acceptable Q'ty	6000	6000	6000	6000	6000	6000	6000	6000	6000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

5. Product :

6. Inspection report:

[illegible]