

Inspection Report

Report No.: XYLA-150412
Supplier : XY-GLOBAL

Inspection Date: 18th May, 2015
Inspector: Leo

Inspection only for: PO . XYLA-150412 Item No. XY31PC022	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC022	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Pass	Fail
1	25.000	25.000	mm	100%	0%
2	40.000	40.000	mm	100%	0%
3	40.000	40.000	mm	100%	0%
4	2.000	2.000	mm	100%	0%
5	2.000	2.000	mm	100%	0%
6	2.000	2.000	mm	100%	0%
7	2.000	2.000	mm	100%	0%
8	2.000	2.000	mm	100%	0%
9	2.000	2.000	mm	100%	0%
10	2.000	2.000	mm	100%	0%
11	2.000	2.000	mm	100%	0%
12	2.000	2.000	mm	100%	0%
13	2.000	2.000	mm	100%	0%
14	2.000	2.000	mm	100%	0%
15	2.000	2.000	mm	100%	0%
16	2.000	2.000	mm	100%	0%
17	2.000	2.000	mm	100%	0%
18	2.000	2.000	mm	100%	0%
19	2.000	2.000	mm	100%	0%
20	2.000	2.000	mm	100%	0%
21	2.000	2.000	mm	100%	0%
22	2.000	2.000	mm	100%	0%
23	2.000	2.000	mm	100%	0%
24	2.000	2.000	mm	100%	0%
25	2.000	2.000	mm	100%	0%
26	2.000	2.000	mm	100%	0%
27	2.000	2.000	mm	100%	0%
28	2.000	2.000	mm	100%	0%
29	2.000	2.000	mm	100%	0%
30	2.000	2.000	mm	100%	0%
31	2.000	2.000	mm	100%	0%
32	2.000	2.000	mm	100%	0%
33	2.000	2.000	mm	100%	0%
34	2.000	2.000	mm	100%	0%
35	2.000	2.000	mm	100%	0%
36	2.000	2.000	mm	100%	0%
37	2.000	2.000	mm	100%	0%
38	2.000	2.000	mm	100%	0%
39	2.000	2.000	mm	100%	0%
40	2.000	2.000	mm	100%	0%
41	2.000	2.000	mm	100%	0%
42	2.000	2.000	mm	100%	0%
43	2.000	2.000	mm	100%	0%
44	2.000	2.000	mm	100%	0%
45	2.000	2.000	mm	100%	0%
46	2.000	2.000	mm	100%	0%
47	2.000	2.000	mm	100%	0%
48	2.000	2.000	mm	100%	0%
49	2.000	2.000	mm	100%	0%
50	2.000	2.000	mm	100%	0%
51	2.000	2.000	mm	100%	0%
52	2.000	2.000	mm	100%	0%
53	2.000	2.000	mm	100%	0%
54	2.000	2.000	mm	100%	0%
55	2.000	2.000	mm	100%	0%
56	2.000	2.000	mm	100%	0%
57	2.000	2.000	mm	100%	0%
58	2.000	2.000	mm	100%	0%
59	2.000	2.000	mm	100%	0%
60	2.000	2.000	mm	100%	0%
61	2.000	2.000	mm	100%	0%
62	2.000	2.000	mm	100%	0%
63	2.000	2.000	mm	100%	0%
64	2.000	2.000	mm	100%	0%
65	2.000	2.000	mm	100%	0%
66	2.000	2.000	mm	100%	0%
67	2.000	2.000	mm	100%	0%
68	2.000	2.000	mm	100%	0%
69	2.000	2.000	mm	100%	0%
70	2.000	2.000	mm	100%	0%
71	2.000	2.000	mm	100%	0%
72	2.000	2.000	mm	100%	0%
73	2.000	2.000	mm	100%	0%
74	2.000	2.000	mm	100%	0%
75	2.000	2.000	mm	100%	0%
76	2.000	2.000	mm	100%	0%
77	2.000	2.000	mm	100%	0%
78	2.000	2.000	mm	100%	0%
79	2.000	2.000	mm	100%	0%
80	2.000	2.000	mm	100%	0%
81	2.000	2.000	mm	100%	0%
82	2.000	2.000	mm	100%	0%
83	2.000	2.000	mm	100%	0%
84	2.000	2.000	mm	100%	0%
85	2.000	2.000	mm	100%	0%
86	2.000	2.000	mm	100%	0%
87	2.000	2.000	mm	100%	0%
88	2.000	2.000	mm	100%	0%
89	2.000	2.000	mm	100%	0%
90	2.000	2.000	mm	100%	0%
91	2.000	2.000	mm	100%	0%
92	2.000	2.000	mm	100%	0%
93	2.000	2.000	mm	100%	0%
94	2.000	2.000	mm	100%	0%
95	2.000	2.000	mm	100%	0%
96	2.000	2.000	mm	100%	0%
97	2.000	2.000	mm	100%	0%
98	2.000	2.000	mm	100%	0%
99	2.000	2.000	mm	100%	0%
100	2.000	2.000	mm	100%	0%

6. report

[illegible]

High qualified surface treatment can make your parts perfect !!!

