

Inspection Report

Report No.: XYN-130814

Supplier : XY-GLOBAL

Inspection Date:02th- Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYN-130814 Item No.1400190	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400190	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC CNC CNC CNC CNC CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
	CNC CNC CNC CNC CNC CNC
	gague
	+/- 0.01MM
	T / T 50 50 T / T .
	T / T 50 25-20
1.Name:	OEM
2.Process:	
3.Material:	AL6061 AL6065 AL6063 AL7075
4.Surface	
5.Tolerance:	0.01 -/+ MM
6 Quality:	100
7.Specification:	OEM
8.	30-25 :
9.	accessoried
10.	AUSTRIAL
11.	ISO 9001
1. 10	
2.	
3. kinds sureface finishment available	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC	ISO9001