

□□□□□□ □□□□□□ □□□□ □□ □□□□□□ □□□□□□□□□□ □□□□□

Inspection Report

Report No.: 130925

Inspection Date: 25th Sep 2013

Supplier :

Inspector: Ken Tung

Inspection only for: Item No. ARM00039	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
ARM	1000sets	100%	12pcs	12pcs poor painting	1000pcs

Appearance Inspection :

No failure,

12pcs poor painting

Dimension Inspection:

No failure , below measurement report for reference.

Leakage Test:

No failure

Inspection Summary

The inspection sample plan are follow AQL , 12pcs poor painting The result of inspection is acceptable.

Digital photo records :



1. Packing

2. Product




3. Product

4. Item number




5. Product

6. Product



7 Customer No.

8. Product



9. Defect-Poor painting

10. Defect-Poor painting



11. Test

12. Test



13. Carton

14. Loading

[illegible]