

□□□□□□□□ □□ □□□□□□□□□□ □□□ □□□□ □□□□ □□□□ □□□□ □□□□ □□□□

## Inspection Report

**Report No.:** XYS-130729  
**Supplier :** XY-GLOBAL

**Inspection Date:** 20<sup>th</sup> Aug, 2013  
**Inspector:** Leo

|                                                               |                                   |
|---------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYS-130729    Item No.XY-1302130 | <u>Inspection Result:</u><br>PASS |
|---------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty  | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|----------------|---------------|--------------|---------------------|-----------------|
| XY-1302130  | <b>2000PCS</b> | 5% inspection | 0pcs         | No failure          | 2000pcs         |

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

[illegible]