

Inspection Report

Report No.: XYL-150717
Supplier : XY-GLOBAL

Inspection Date: 29th Aug, 2015
Inspector: Leo

Inspection only for: PO : XYL-150717 Item No. XY11LM017	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM017	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

检查报告

品名	规格	数量	单位	检验日期	检验员
XY11LM017	XY11LM017	12000	PCS	2015.08.29	Leo
检验项目	检验标准	检验结果	判定	检验日期	检验员
外观	无缺陷	合格	合格	2015.08.29	Leo
尺寸	符合图纸	合格	合格	2015.08.29	Leo
重量	符合图纸	合格	合格	2015.08.29	Leo
硬度	符合图纸	合格	合格	2015.08.29	Leo
拉力	符合图纸	合格	合格	2015.08.29	Leo
冲击	符合图纸	合格	合格	2015.08.29	Leo
疲劳	符合图纸	合格	合格	2015.08.29	Leo
耐腐蚀	符合图纸	合格	合格	2015.08.29	Leo
电性能	符合图纸	合格	合格	2015.08.29	Leo
热性能	符合图纸	合格	合格	2015.08.29	Leo
环境性能	符合图纸	合格	合格	2015.08.29	Leo
可靠性	符合图纸	合格	合格	2015.08.29	Leo
寿命	符合图纸	合格	合格	2015.08.29	Leo
安全	符合图纸	合格	合格	2015.08.29	Leo
环保	符合图纸	合格	合格	2015.08.29	Leo
其他	符合图纸	合格	合格	2015.08.29	Leo

6. Report:

[illegible]

High qualified surface treatment can make your parts perfect !!!

