

Inspection Report

Report No.: XYGA-150310

Inspection Date: 15th Apr., 2015

Supplier: XY-GLOBAL

Inspector: LEO

Inspection only for:	Inspection Result:
PO: XYGA-140310 Item No. XY21ZC050	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC050	5000pcs	7% inspection	0pcs	No failure	5000pcs

Appearance Inspection:

No failure,

Dimension Inspection:

No failure, below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records:



1. Packing



2. Product:



3. Product:



4. Product:



5. Product:

XY21ZC050									
Item	Spec	Actual	Unit	Min	Max	Min	Max	Min	Max
1	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
2	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
3	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
4	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
5	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
6	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
7	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
8	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
9	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
10	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
11	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
12	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
13	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
14	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
15	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
16	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
17	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
18	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
19	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
20	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
21	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
22	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
23	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
24	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
25	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
26	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
27	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
28	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
29	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
30	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
31	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
32	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
33	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
34	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
35	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
36	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
37	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
38	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
39	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
40	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
41	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
42	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
43	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
44	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
45	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
46	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
47	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
48	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
49	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00
50	XY21ZC050	XY21ZC050	mm	0.00	0.00	0.00	0.00	0.00	0.00

6. Inspection report:

[illegible]