

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYSL-150616 Item No. XY31XL014	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL014	9000PCS	1% inspection	Opcs	No failure	9000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

podmis		KOD 2011-128		K. A. K. K.		K. A. K. K.	
A	1.00	0.00	0.00	0.00	0.00	0.00	0.00
B	1.00	0.00	0.00	0.00	0.00	0.00	0.00
C	1.00	0.00	0.00	0.00	0.00	0.00	0.00
D	1.00	0.00	0.00	0.00	0.00	0.00	0.00
E	1.00	0.00	0.00	0.00	0.00	0.00	0.00
F	1.00	0.00	0.00	0.00	0.00	0.00	0.00
G	1.00	0.00	0.00	0.00	0.00	0.00	0.00
H	1.00	0.00	0.00	0.00	0.00	0.00	0.00
I	1.00	0.00	0.00	0.00	0.00	0.00	0.00
J	1.00	0.00	0.00	0.00	0.00	0.00	0.00
K	1.00	0.00	0.00	0.00	0.00	0.00	0.00
L	1.00	0.00	0.00	0.00	0.00	0.00	0.00
M	1.00	0.00	0.00	0.00	0.00	0.00	0.00
N	1.00	0.00	0.00	0.00	0.00	0.00	0.00
O	1.00	0.00	0.00	0.00	0.00	0.00	0.00
P	1.00	0.00	0.00	0.00	0.00	0.00	0.00
Q	1.00	0.00	0.00	0.00	0.00	0.00	0.00
R	1.00	0.00	0.00	0.00	0.00	0.00	0.00
S	1.00	0.00	0.00	0.00	0.00	0.00	0.00
T	1.00	0.00	0.00	0.00	0.00	0.00	0.00
U	1.00	0.00	0.00	0.00	0.00	0.00	0.00
V	1.00	0.00	0.00	0.00	0.00	0.00	0.00
W	1.00	0.00	0.00	0.00	0.00	0.00	0.00
X	1.00	0.00	0.00	0.00	0.00	0.00	0.00
Y	1.00	0.00	0.00	0.00	0.00	0.00	0.00
Z	1.00	0.00	0.00	0.00	0.00	0.00	0.00

6. report

[illegible]

Safety is our serious job for our worker and engineer team

