

□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYD-130703
Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130703 Item No.XY-956400	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-956400	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

0000	000 000000000000000000000000 00000000OEM0000000000 000
00	0 ADC120A3800
00	0 00000
0000	0 000000000000000000000000 0000
00	0 00000000
0000	00 0000000000000000 0000000000000000
0000	00 00000000gague000000000000 000000000000000000000000 000000000000000000000000 0
00000	00
00/00	+/-0.0100
00	T / T 500000000500T / T0000000
0000	00 000000000000000000000000 0000000000000000000000
00	000 0000000000000000000000 0000000000000000
00	000 00
00	20-25&NBSP;0 T / T 5000000
0000	00 00000
1.Name0 0000000000	
2.Process0000000000	
00000000ADC120A3800	
4.0000000000000000000000 0000	
5.Tolerance0000±0.0100	
6.00000100000	
7.Specification000serice0000000000	
800000025-3000000000	
900000000000000000 00accessoried00000000	
1000000000000Austrial000000	
11&NBSP;000ISO 9001	
00000	
1001000000ISO00	
20000000	
3000000000kindls0abailable	
4000000000000	
5000000	
600000	
70000000000000	
00000	
00000000&NBSP;0000000000 00	
00000000000000	
0000000000ISO9001	
0000000000000000 00	
00000000OEM000	