

Inspection Report



Report No.: XYS-130723
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130723 Item No.XY-300985	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-300985	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

00000	0000 0000000000 0000000000 0000000000 OEM 0000000000 0000
00	0 ADC120A3800
00	0 000000
00000	0 000000000000000000000000 00000
00	0 0000000000
00000	00 0000000000000000 000000000000000000
00000	00 0000000000gague00000000000000 000000000000000000000000 00000000000000000000000000 0
000000	00
00/00	+/-0.0100
00	T / T 5000000000500T / T00000000
00000	00 000000000000000000000000 000000000000000000
00	0000 00000000000000000000 000000000000000000
00	0000 00
00	20-25&NBSP;0 T / T 50000000
00000	00 000000
10 0000000000OEM 00000000	
2.Process000000000000	
0000000000ADC120A3800	
4.000000000000000000000000 00000	
5.Tolerance0000±0.0100	
6.000000100000	
7.Specification0000serice000000000000	
8000000025-300000000000	
90000000000000000000 00accessoried0000000000	
10000000000000000000Austrial000000	
11&NBSP;0000ISO 9001	
0000000	
1010000000ISO00	
2000000000	
30000000000kindls0available	
4000000000000000	
50000000	
60000000	
7000000000000000	
0000000	
00000000&NBSP;00000000000 00	
000000000000000000	
000000000000ISO9001	
000000000000000000 00	
0000000000OEM0000	