

Inspection Report

Report No.: XYLA-150314

Supplier : XY-GLOBAL

Inspection Date: 18th Apr, 2015

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO : XYLA-150314 Item No. XY31PC010	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC010	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Pass/Fail
1	1.0000	1.0000	mm	Pass
2	1.0000	1.0000	mm	Pass
3	1.0000	1.0000	mm	Pass
4	1.0000	1.0000	mm	Pass
5	1.0000	1.0000	mm	Pass
6	1.0000	1.0000	mm	Pass
7	1.0000	1.0000	mm	Pass
8	1.0000	1.0000	mm	Pass
9	1.0000	1.0000	mm	Pass
10	1.0000	1.0000	mm	Pass
11	1.0000	1.0000	mm	Pass
12	1.0000	1.0000	mm	Pass
13	1.0000	1.0000	mm	Pass
14	1.0000	1.0000	mm	Pass
15	1.0000	1.0000	mm	Pass
16	1.0000	1.0000	mm	Pass
17	1.0000	1.0000	mm	Pass
18	1.0000	1.0000	mm	Pass
19	1.0000	1.0000	mm	Pass
20	1.0000	1.0000	mm	Pass
21	1.0000	1.0000	mm	Pass
22	1.0000	1.0000	mm	Pass
23	1.0000	1.0000	mm	Pass
24	1.0000	1.0000	mm	Pass
25	1.0000	1.0000	mm	Pass
26	1.0000	1.0000	mm	Pass
27	1.0000	1.0000	mm	Pass
28	1.0000	1.0000	mm	Pass
29	1.0000	1.0000	mm	Pass
30	1.0000	1.0000	mm	Pass
31	1.0000	1.0000	mm	Pass
32	1.0000	1.0000	mm	Pass
33	1.0000	1.0000	mm	Pass
34	1.0000	1.0000	mm	Pass
35	1.0000	1.0000	mm	Pass
36	1.0000	1.0000	mm	Pass
37	1.0000	1.0000	mm	Pass
38	1.0000	1.0000	mm	Pass
39	1.0000	1.0000	mm	Pass
40	1.0000	1.0000	mm	Pass
41	1.0000	1.0000	mm	Pass
42	1.0000	1.0000	mm	Pass
43	1.0000	1.0000	mm	Pass
44	1.0000	1.0000	mm	Pass
45	1.0000	1.0000	mm	Pass
46	1.0000	1.0000	mm	Pass
47	1.0000	1.0000	mm	Pass
48	1.0000	1.0000	mm	Pass
49	1.0000	1.0000	mm	Pass
50	1.0000	1.0000	mm	Pass
51	1.0000	1.0000	mm	Pass
52	1.0000	1.0000	mm	Pass
53	1.0000	1.0000	mm	Pass
54	1.0000	1.0000	mm	Pass
55	1.0000	1.0000	mm	Pass
56	1.0000	1.0000	mm	Pass
57	1.0000	1.0000	mm	Pass
58	1.0000	1.0000	mm	Pass
59	1.0000	1.0000	mm	Pass
60	1.0000	1.0000	mm	Pass
61	1.0000	1.0000	mm	Pass
62	1.0000	1.0000	mm	Pass
63	1.0000	1.0000	mm	Pass
64	1.0000	1.0000	mm	Pass
65	1.0000	1.0000	mm	Pass
66	1.0000	1.0000	mm	Pass
67	1.0000	1.0000	mm	Pass
68	1.0000	1.0000	mm	Pass
69	1.0000	1.0000	mm	Pass
70	1.0000	1.0000	mm	Pass
71	1.0000	1.0000	mm	Pass
72	1.0000	1.0000	mm	Pass
73	1.0000	1.0000	mm	Pass
74	1.0000	1.0000	mm	Pass
75	1.0000	1.0000	mm	Pass
76	1.0000	1.0000	mm	Pass
77	1.0000	1.0000	mm	Pass
78	1.0000	1.0000	mm	Pass
79	1.0000	1.0000	mm	Pass
80	1.0000	1.0000	mm	Pass
81	1.0000	1.0000	mm	Pass
82	1.0000	1.0000	mm	Pass
83	1.0000	1.0000	mm	Pass
84	1.0000	1.0000	mm	Pass
85	1.0000	1.0000	mm	Pass
86	1.0000	1.0000	mm	Pass
87	1.0000	1.0000	mm	Pass
88	1.0000	1.0000	mm	Pass
89	1.0000	1.0000	mm	Pass
90	1.0000	1.0000	mm	Pass
91	1.0000	1.0000	mm	Pass
92	1.0000	1.0000	mm	Pass
93	1.0000	1.0000	mm	Pass
94	1.0000	1.0000	mm	Pass
95	1.0000	1.0000	mm	Pass
96	1.0000	1.0000	mm	Pass
97	1.0000	1.0000	mm	Pass
98	1.0000	1.0000	mm	Pass
99	1.0000	1.0000	mm	Pass
100	1.0000	1.0000	mm	Pass

6. report

[illegible]

Safety is our serious job for our worker and engineer team

