

□□□A380□□□□□□□□□□

Inspection Report

Report No.: XYS-130711
Supplier : XY-GLOBAL

Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130711 Item No.XY-3519400	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-3519400	4000PCS	5% inspection	0pcs	No failure	4000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

0000	0000 000000000000000000000000 OEM0000000000 0000
00	0 ADC120A3800
00	0 000000
0000	0 000000000000000000000000 0000
00	0 0000000000
0000	00 0000000000000000 000000000000000000
0000	00 00000000gague000000000000 000000000000000000000000 000000000000000000000000 0
000000	00
00/00	+/-0.0100
00	T / T 5000000000500T / T00000000
0000	00 000000000000000000000000 000000000000000000
00	000 0000000000000000000000 000000000000000000
00	000 00
00	20-25&NBSP;0 T / T 50000000
0000	00 000000
1.Name0 00000000000	
2.Process0000000000	
00000000ADC120A3800	
4.0000000000000000000000 0000	
5.Tolerance0000±0.0100	
6.000000100000	
7.Specification000serice0000000000	
8000000025-3000000000	
900000000000000000 00accessoried00000000	
10000000000000Austrial000000	
11&NBSP;000ISO 9001	
000000	
10 10000000ISO00	
20000000	
300000000kindls0abailable	
40000000000000	
50000000	
6000000	
70000000000000	
000000	
00000000NBSP;0000000000 00	
00000000000000	
0000000000ISO9001	
0000000000000000 00	
00000000OEM0000	