

Inspection Report

Report No.: XYNK-130809

Supplier : XY-GLOBAL

Inspection Date:10th Sep-, 2013

Inspector:LEO

Inspection only for:	Inspection Result:
PO . XYNK-130809 Item No.1402289	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402289	6000Pcs	100% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

項目	項目詳細説明項目詳細説明項目詳細説明OEM項目詳細説明
項目	項目ADC12項目A380項目
項目	項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明
項目/項目	+/-0.01項目
項目	項目50項目項目項目項目項目50項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目
項目	項目50項目項目25項目
項目	項目項目項目項目項目
1.項目項目項目項目項目	
2.項目項目項目項目項目項目項目項目	
3.項目項目項目ADC12項目A380項目	
4.項目項目項目項目項目項目項目項目項目項目	
5.項目項目項目±0.01項目	
6.項目項目項目100項目	
7.項目項目項目項目項目項目項目項目項目項目	
8.項目項目項目25-30項目	
9.項目項目項目項目項目項目項目項目項目項目項目項目項目項目項目項目	
10.項目項目項目項目項目項目項目項目項目項目	
11.項目項目項目項目ISO 9001	
項目項目	
1.10項目項目項目ISO項目	
2.項目項目項目項目項目項目項目項目	
3.項目項目項目項目項目項目項目項目	
4.項目項目項目項目項目	
5.項目項目	
6.項目項目	
7.項目項目項目項目項目項目	
項目項目	
項目項目項目項目項目項目項目項目項目項目	
項目項目項目項目項目	
項目項目項目項目ISO9001	
項目項目項目項目項目項目項目項目	
項目OEM項目項目項目項目	