

Inspection Report

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYSL-150625 Item No. XY31XL023	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL023	10000PCS	1% inspection	Opes	No failure	10000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

podmínky		KAPPA 2011 100%		1. a 2. KAPPA	
1	2	3	4	5	6
A	100% 100%	0,00%	0,00%	0,00%	0,00%
B	100% 100%	0,00%	0,00%	0,00%	0,00%
C	100% 100%	0,00%	0,00%	0,00%	0,00%
D	100% 100%	0,00%	0,00%	0,00%	0,00%
E	100% 100%	0,00%	0,00%	0,00%	0,00%
F	100% 100%	0,00%	0,00%	0,00%	0,00%
G	100% 100%	0,00%	0,00%	0,00%	0,00%
H	100% 100%	0,00%	0,00%	0,00%	0,00%
I	100% 100%	0,00%	0,00%	0,00%	0,00%
J	100% 100%	0,00%	0,00%	0,00%	0,00%
K	100% 100%	0,00%	0,00%	0,00%	0,00%
L	100% 100%	0,00%	0,00%	0,00%	0,00%
M	100% 100%	0,00%	0,00%	0,00%	0,00%
N	100% 100%	0,00%	0,00%	0,00%	0,00%
O	100% 100%	0,00%	0,00%	0,00%	0,00%
P	100% 100%	0,00%	0,00%	0,00%	0,00%
Q	100% 100%	0,00%	0,00%	0,00%	0,00%
R	100% 100%	0,00%	0,00%	0,00%	0,00%
S	100% 100%	0,00%	0,00%	0,00%	0,00%
T	100% 100%	0,00%	0,00%	0,00%	0,00%
U	100% 100%	0,00%	0,00%	0,00%	0,00%
V	100% 100%	0,00%	0,00%	0,00%	0,00%
W	100% 100%	0,00%	0,00%	0,00%	0,00%
X	100% 100%	0,00%	0,00%	0,00%	0,00%
Y	100% 100%	0,00%	0,00%	0,00%	0,00%
Z	100% 100%	0,00%	0,00%	0,00%	0,00%

6. report

[illegible]

Safety is our serious job for our worker and engineer team

