

Inspection Report



Report No.: XYS-130723
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130723 Item No.XY-300985	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-300985	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

項目	項目 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄
項目	項目 ADC12項目A380項目
項目	項目 詳細説明欄
項目	項目 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄
項目	項目 詳細説明欄 詳細説明欄
項目	CNC 詳細説明欄 詳細説明欄 詳細説明欄
項目	項目 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄
MOQ	項目
項目/項目	+/-0.01項目
項目	T / T 項目50項目項目50項目T / T;項目
項目	CNC 詳細説明欄 詳細説明欄 詳細説明欄
項目	項目 詳細説明欄 詳細説明欄 詳細説明欄 詳細説明欄
項目	項目 項目
項目	20-25項目項目T / T 50項目
項目	項目 詳細説明欄
1.項目項目OEM項目	
2.項目項目cnc項目	
3.項目項目ADC12項目A380項目	
4.項目項目項目項目項目項目項目項目	
項目項目+/- 0.01mm	
項目項目100項目	
7.項目OEM項目項目項目項目項目	
8.項目項目項目項目25-30項目	
9.項目項目項目項目項目項目項目項目	
10.項目項目項目項目項目項目項目項目	
11.項目ISO 9001	
項目項目	
1項目10項目ISO項目項目	
項目項目項目	
項目項目項目項目項目項目項目項目	
項目項目項目項目項目項目	
項目項目	
項目項目	
7.項目項目項目項目項目	
項目項目	
項目項目項目項目項目項目項目項目	
項目項目項目項目項目項目項目項目	
項目項目ISO9001	
項目項目項目項目項目項目項目項目	
項目項目OEM項目項目項目	

項目項目項目項目項目項目項目項目