

Inspection Report



Report No.: XYJ-140315
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYJ-140315 Item No. 2480112	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2480112	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4. Product
	
5. Product:	6. Product:

	0000 00000000000000000000 OEM0000000000 000
00	ADC12A380
00	0 00000
0000	0 0000000000000000000000 0000
00	0 00000000
0000	00 0000000000000000 0000000000000000
0000	00 0000000gague000000000000 00000000000000000000 0000000000000000000000 0
00000	00
00/00	+/-0.01
00	T / T 5000000050T / T0000000
0000	00 000000000000000000 000000000000000000
00	000 000000000000000000 0000000000000000
00	000 00
00	20-25&NBSP;T / T 5000000
0000	00 000000
1.Name0 0000000000	
2.Process0000000000	
00000000ADC12A380	
4.00000000000000000000 0000	
5.Tolerance0000±0.01	
6.000000100000	
7.Specification000serice0000000000	
800000025-3000000000	
900000000000000000 00accessoried00000000	
1000000000000Austrial000000	
11&NBSP;000ISO 9001	
000000	
11000000ISO00	
200000000	
300000000kindlsavailable	
4000000000000	
50000000	
6000000	
70000000000000	
000000	
0000000&NBSP;0000000000 00	
0000000000000000	
0000000000ISO9001	
0000000000000000 00	
00000000OEM000	