

Inspection Report

Report No.: XYL-150729
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150729 Item No. XY11LM029	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM029	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	0000 0000000000000000000000 0000000OEM0000000000 00
	0 ADC120A3800
0000	00 000000
0000	0 0000000000000000000000 0000
00	0 000000000000
0000	CNC 0000000000000000 0000000000000000
0000	00 000000gague000000000000 000000000000000000 00000000000000000000 0
MOQ	00
00/00	+/-0.0100
00	T / T 0050000050T / T000;0000
0000	CNC 0000000000000000000000 0000000000000000
00	0000 00000000000000000000 0000000000000000
00	0000 00
00	20-25 T / T 50000000
0000	00 000000
1.Name0 000OEM0000000	
2.Process0 000000000000	
3.000 000ADC120A3800	
4.0000000 0000000000000000	
5.Tolerance0 0000+/-0.0100	
6.00 000100000	
7.Specification0 OEM0000000000000000	
80 000000025-3000000000	
90 00000000000000000000 accessoried00000000	
100 000000000000Austrial00000	
11.000 ISO 9001	
000000	
10 0ISO000100000	
20 000000	
30 sureface00000kindls0available	
40 000000000000	
50 00000	
60 0000	
70 0000000000000000	
000000	
0 00000000000000	
0 000000000000	
0 0000000ISO9001	
0 0000000000000000	
0 000OEM0000	

Safety is our serious job for our worker and engineer team

