

Inspection Report

Report No.: XYL-150806
Supplier : XY-GLOBAL

Inspection Date: 17th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150806 Item No. XY11XL049	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11XL049	17000PCS	1% inspection	0pcs	No failure	17000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

検査報告									
品名	規格	検査項目	検査結果	検査方法	検査場所	検査日	検査員	検査時間	検査回数
XY11XL049	XY11XL049	外形寸法	OK	目視	工場	2015.09.17	Leo	10分	1回
XY11XL049	XY11XL049	機能試験	OK	電気試験	工場	2015.09.17	Leo	30分	1回
XY11XL049	XY11XL049	組立試験	OK	組立試験	工場	2015.09.17	Leo	10分	1回
XY11XL049	XY11XL049	最終検査	OK	目視	工場	2015.09.17	Leo	10分	1回
XY11XL049	XY11XL049	合計	OK						

6. Report:

	OEM
ADC12A380	
	+/-0.01
	5050
	5025
1.	
2.	
3.ADC12A380	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

High qualified surface treatment can make your parts perfect !!!

