

## Inspection Report

**Supplier :** XY-GLOBAL

**Inspector: Leo**

|                                                                |                                   |
|----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYLA-150406    Item No. XY31PC016 | <u>Inspection Result:</u><br>PASS |
|----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31PC016   | 15000PCS      | 1% inspection | Opes         | No failure          | 15000pcs        |

**Appearance Inspection :**

|             |
|-------------|
| No failure. |
|-------------|

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

## Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. report

[illegible]

High qualified surface treatment can make your parts perfect !!!

