

Inspection Report

Report No.: XYL-150811
Supplier : XY-GLOBAL

Inspection Date: 20th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150811 Item No. XY11LM041	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM041	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product

検査報告									
品名	規格	数量	検査項目	検査結果	検査方法	検査場所	検査日時	検査者	検査結果
XY11LM041	XY11LM041	16000	外形寸法	OK	目視・計測	XY-GLOBAL	2015.09.20	Leo	合格
XY11LM041	XY11LM041	16000	機能試験	OK	電気試験	XY-GLOBAL	2015.09.20	Leo	合格
XY11LM041	XY11LM041	16000	組立試験	OK	組立試験	XY-GLOBAL	2015.09.20	Leo	合格
XY11LM041	XY11LM041	16000	最終検査	OK	最終検査	XY-GLOBAL	2015.09.20	Leo	合格

6. Report:

	OEM
	ADC12A380
	+/-0.01
	50 50
	50 25
1.	
2.	
3.ADC12A380	
4.	
5. ± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11.ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

