

Inspection Report

Report No.: XYSK-140617
Supplier : XY-GLOBAL

Inspection Date: 10th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140617 Item No. XY31SY017	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY017	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Client Name: XY-GLOBAL	Product Type: XY31SY017	Inspection Date: 10/07/2014	Inspector: Leo
Part No: XY31SY017	Lot No: 140617	Quantity: 10000	Sample Size: 100

Inspection Method: 100% inspection

Inspection Results:

Defect No.	Defect Description	Defect Count	Defect Rate
1	Surface scratch	0	0%
2	Dimension deviation	0	0%
3	Material defect	0	0%
4	Color deviation	0	0%
5	Surface contamination	0	0%
6	Internal defect	0	0%
7	Surface deformation	0	0%
8	Surface discoloration	0	0%
9	Surface oxidation	0	0%
10	Surface corrosion	0	0%
11	Surface cracking	0	0%
12	Surface pitting	0	0%
13	Surface blistering	0	0%
14	Surface delamination	0	0%
15	Surface peeling	0	0%
16	Surface flaking	0	0%
17	Surface chipping	0	0%
18	Surface abrasion	0	0%
19	Surface erosion	0	0%
20	Surface corrosion	0	0%

Inspection Conclusion: All items passed inspection.

Inspector: Leo

6. report

11

[illegible]

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□□□ □□□□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 100000 ISO 100

2. □□□□□□□□□□□□

3. □□□□□□□□□□□□

4.

5. □□□□□

6.□□□□□□

7. □□□□□□□□□□□□□□□□

[illegible][illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
