

Inspection Report

Report No.: XYS-131017

Supplier : XY-GLOBAL

Inspection Date: 9th Nov-, 2013

Inspector: LEO

Inspection only for: PO . XYS-131017 Item No.XY-MST-059	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-059	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	加工 品名	加工 品名
	CNC加工 品名	CNC加工 品名
	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316	
	CNC加工 品名	
	gague加工 品名	
	+/-0.01	
	T / T 50T / T	
	T / T 5020-25 NBSP	
	1.Name CNC加工 品名	
	2.Process	
	AL6061 AL6065AL6063AL7075	
	4.	
	5.Tolerance±0.01	
	6.100	
	7.Specificationserice	
	8.25-30	
	9.accessoried	
	10.Austrial	
	11&NBSP;ISO 9001	
	1.10ISO	
	2.	
	3.kindlsavailable	
	4.	
	5.	
	6.	
	7.	
	&NBSP;	
	ISO9001	