

□□□A356□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130514
Supplier : XY-GLOBAL

Inspection Date: 04th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130514 Item No.XY-1300291	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300291	2000PCS	5% inspection	0pcs	No failure	2000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

	0000 0000000000000000 0000000000000000 OEM0000000000000000 0000
000000	000000 ADC12A38000
00	000 00000000
0000	000 000000000000000000000000000000 000000
000000	000 00000000000000000000
0000	CNC 000000000000000000000000 CNC00000
0000	00 0000000000gague000000000000000000000000 0000000000000000000000000000000000 00 00 00
MOQ	00
00/00	+/- 0.01000000
000	T / T 5050T / T0000000000;00
0000	CNC 0000000000000000CNC0000000000000000 0000-0000000000000000
00000000	000 000000000000000000000000 000000000000000000000000
000	000 00
00	20-25&NBSP000 T / T 50000000
0000	00 00000000
1.Name	00000000OEM0000000000
2.Process	0000000000CNC000000
3.	000000ADC12A38000
4.Surface	0000000000000000nickle000000 00000000
5.Tolerance	000 +/- 0.010000000000000000
6	0000000100000
7.Specification	0OEM0000000000000000
8	000000000000000025-30000
9	000000000000000000000000000000 00accessoried00000000
10	0000000000000000AustrialEU00
11&NBSP	00000ISO 9001
000000	
ISO	00000110000000
2	000000000000000000
3 sureface	finishment000kindlsavailable00
00000000000000004	
5	00000000
00006	00000
7	0000000000000000
00000000	
000000000000&NBSP	0000000000000000000000 000
0000000000000000	
0000000000000000ISO9001	
000000000000000000	0000000
OEM	0000000000000000