

Inspection Report


Report No.: XYD-140509
Supplier : XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYD-140509 Item No.XY-141325	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141325	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

ชื่อ	บริษัท. จำกัดOEM
วัสดุ	ADC12A380
รูป	รูป
ขนาด	รูป
สี	CNC
MOQ	รูป
ราคา/ชิ้น	+/- 0.01
รูป	T / T 50T / T
รูป	CNC
รูป	รูป
รูป	20-25T / T 50
รูป	รูป
1.Name	บริษัท. จำกัดOEM
2.Process	CNC
3.	ADC12A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	AustrialEU
11&NBSP	ISO 9001
รูป	
ISO	110
2.	
3.sureface	finishmentkindlsavailable
รูป	4
5.	
รูป	6
7.	
รูป	
รูป	&NBSP
รูป	
รูป	ISO9001
รูป	
OEM	