

Inspection Report

Report No.: XYDA-140516
Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYDA-140516 Item No.1466800	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1466800	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Part Name	Part Name OEM Part Name
Part Number	Part Number ADC12 A380
Material	Material
Surface	Surface
Process	Process CNC
MOQ	MOQ
Tolerance	Tolerance +/- 0.01
Lead Time	Lead Time T / T 50
Payment	Payment
Delivery	Delivery
Accessories	Accessories
ISO	ISO
1.Name	1.Name OEM
2.Process	2.Process CNC
3.Material	3.Material ADC12 A380
4.Surface	4.Surface nickle
5.Tolerance	5.Tolerance +/- 0.01
6.Quantity	6.Quantity 100
7.Specification	7.Specification OEM service
8.Delivery	8.Delivery 25 30
9.Accessories	9.Accessories accessoried
10.Austrial	10.Austrial EU
11.ISO 9001	11.ISO 9001
ISO 1.10	ISO 1.10
2. sureface	2. sureface finishment
3. kindls	3. kindls available
4. ISO	4. ISO
5. ISO	5. ISO
6. ISO	6. ISO
7. ISO	7. ISO
8. ISO	8. ISO
9. ISO	9. ISO
10. ISO	10. ISO
11. ISO	11. ISO
OEM	OEM