

Inspection Report

Report No.: XYD-130801
Supplier : XY-GLOBAL

Inspection Date:11th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYD-130801 Item No.1400024	<u>Inspection Result:</u> PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400024	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

	CNC
	AL6061 AL6065AL6063AL7075&NBSP SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 5050T / T;
	CNC CNC CNC CNC
	CNC
	20-25&NBSPT / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6100	
7.Specification OEM	
825-30	
9CNC accessoried	
10Austrial EU	
11&NBSP ISO 9001	
ISO110	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
CNC&NBSP	
CNC	
CNC ISO9001	
CNC	
CNC OEM	