

Inspection Report

Report No.: XYSL-140618

Inspection Date: 25th Jul, 2014

Supplier: XY-GLOBAL

Inspector: Leo

Inspection only for:	Inspection Result:
PO: XYSL-140618 Item No. XY11WD041	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD041	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure, below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product 
5. Product:	6. The test report

000000	0000 000000000000000000000000000000 000000OEM00000000000000000000 0000
00	000000 ADC120A38000
000	00000 00000000
0000	0 0000000000000000000000000000 00000
00000	00 00000000000000000000
0000	CNC 000000000000000000000000 000000000000CNC0000
000000	00 0000000000gague00000000000000000000 0000000000000000000000000000 0000 000000000000000000000000000000000000 00
MOQ	000000
00/00	+/- 0.01000000
000	T / T 500500T / T000000000;00
0000	CNC 0000000000000000CNC000000000000 00000000000000000000
00000000	00000000 000000000000000000000000 000000000000000000000000
000	000 00
00	200250 T / T 500000000
0000	00 00000000
1.Name00000OEM0000000000	
2.Process0000000000CNC00	
3.Material0000ADC120A38000	
4.Surface00000000000000nickle00000 00000	
5.Tolerance000+/- 0.010000000000000000	
600000000000100000	
7.Specification0OEM0serice00000000000000	
8.00000000000025030000	
9.0000000000000000000000000000 00accessoried00000000	
10.00000000000000Austrial0EU00	
11.000ISO 9001	
0000000000	
ISO001. 10000000	
2.000000000000000000	
3. sureface0finishment0000kindls0abailable00	
000000004.000	
5.000000	
00006.0000	
7.0000000000000000	
00000000	
0000000000000000000000000000 000	
000000000000000000	
0000000000000000ISO9001	
000000000000000000 000000	
OEM000000000000000000	