

Inspection Report

Report No.: XYBA-140923

Supplier : XY-GLOBAL

Inspection Date: 18th Oct-, 2014

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYBA-140923 Item No. XY21ZC016	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC016	2000pcs	7% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.


Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

	CNC 零件加工服務CNC精密加工CNC機械加工CNC零件加工CNC機件加工
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC 零件加工服務CNC精密加工CNC機械加工CNC零件加工CNC機件加工
	gague
MOQ	
/	+/- 0.01
T / T	50T / T;
	CNC零件加工CNC精密加工CNC機械加工CNC零件加工CNC機件加工
	CNC零件加工CNC精密加工CNC機械加工CNC零件加工CNC機件加工
	20-25T / T 50
	CNC零件加工
1.NameOEM CNC	
2.ProcessCNC	
3.MaterialAL6061 AL6065AL6063AL7075 POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6.100	
7.SpecificationOEMservice	
8.2530	
9.CNCaccessoried	
10.AustrialEU	
11.ISO 9001	
ISO1. 10	
2.	
3.surefacefinishmentkindlsavailable	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNCISO9001	
CNC	
CNCOEM	