

Inspection Report

Report No.: XYJ-1308025

Supplier : XY-GLOBAL

Inspection Date:19th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYJ-130825 Item No.1401523	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1401523	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

	CNC
	AL6061 AL6065AL6063AL7075&NBSP SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
	+/- 0.01
	T / T 5050T / T;
	CNC
	20-25&NBSPT / T 50
	CNC
1.Name OEM CNC	
2.ProcessCNC	
3.AL6061 AL6065AL6063AL7075POM	
4.Surfacenickle	
5.Tolerance+/- 0.01	
6100	
7.SpecificationOEM	
825-30	
9CNCaccessoried	
10AustrialEU	
11&NBSPISO 9001	
ISO110	
2	
3 surefacefinishmentkindlsabailable	
4	
5	
6	
7	
CNC&NBSP	
CNC	
CNCISO9001	
CNC	
CNCOEM	