

Inspection Report

Report No.: XYDA-140509

Inspection Date: 8th Jun, 2014

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYDA-140509 Item No.1430132	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1430132	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

Part Name	Part Name OEM Part Name
Material	Material ADC12 A380
Surface	Surface
Tolerance	Tolerance
MOQ	MOQ
Lead Time	Lead Time
Payment	Payment
Shipping	Shipping
Warranty	Warranty
1. Name	1. Name OEM Part Name
2. Process	2. Process CNC
3. Material	3. Material ADC12 A380
4. Surface	4. Surface nickel
5. Tolerance	5. Tolerance +/- 0.01
6. MOQ	6. MOQ 100
7. Specification	7. Specification OEM service
8. Lead Time	8. Lead Time 25 30
9. Accessory	9. Accessory accessoried
10. Certification	10. Certification Austrial EU
11. ISO 9001	11. ISO 9001
ISO 9001	ISO 9001
2. sureface	2. sureface finishment kinds available
4. Lead Time	4. Lead Time
5. MOQ	5. MOQ
6. Lead Time	6. Lead Time
7. Certification	7. Certification
ISO 9001	ISO 9001
OEM	OEM