

Inspection Report



Report No.: XYS-130723
Supplier : XY-GLOBAL

Inspection Date: 15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130723 Item No.XY-300985	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-300985	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

	00000 0000000000000000 00000000000000 00000000000000OEM0000000000000000 0000
000000	000000 ADC12A38000
00	000 0000000
0000	000 000000000000000000000000000000 00000
00000	000 00000000000000000000
0000	CNC 0000000000000000000000000000 000000000000CNC0000
0000	00 0000000000gague0000000000000000000000 000000000000000000000000000000 00 00 00
MOQ	00
00/00	+/- 0.01000000
000	T / T 5050T / T0000000000;00
0000	CNC 0000000000000000CNC000000000000 0000-0000000000000000
00000000	000 000000000000000000000000 000000000000000000000000
000	000 00
00	20-25&NBSP000 T / T 50000000
0000	00 00000000
1000000000OEM0000000000	
2.Process0000000000CNC00000	
3.000000ADC12A38000	
4.Surface0000000000000000nickle00000 00000000	
5.Tolerance000 +/- 0.010000000000000000	
6000000100000	
7.Specification0OEM0000000000000000	
800000000000000025-30000	
900000000000000000000000000000 00accessoried00000000	
1000000000000000AustrialEU00	
11&NBSP00000ISO 9001	
000000	
ISO00000110000000	
200000000000000000	
3 surefacefinishment000kindlsavailable00	
000000000000040	
50000000	
0000600000	
7000000000000000	
00000000	
000000000000&NBSP000000000000000000 000	
00000000000000000	
00000000000000ISO9001	
000000000000000000 000000	
OEM0000000000000000	