

□□□□□□□□□□□□□□□□

Inspection Report


Report No.: XYS-130727
Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130727 Item No.XY-1832500	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1832500	100PCS	5% inspection	0pcs	No failure	100pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

	1.Name	OEM
	2.Process	CNC
	3.	ADC12A380
	4.Surface	nickle
	5.Tolerance	+/- 0.01
	6.	100
	7.Specification	OEM
	8.	25-30
	9.	accessoried
	10.	AustrialEU
	11&NBSP	ISO 9001
	ISO	110
	2.	
	3.surefacefinishment	kindlsavailable
		4
	5.	
		6
	7.	
	&NBSP	
		ISO9001
	OEM	