

Inspection Report

Report No.: XYBA-140924

Supplier : XY-GLOBAL


Inspection Date: 20th Oct., 2014

Inspector: LEO

Inspection only for:	Inspection Result:
PO : XYBA-140924 Item No. XY21ZC017	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC017	2000pcs	7% inspection	0pcs	No failure	2000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

	CNC 鋁板加工CNC不銹鋼加工CNC銅板加工CNC鋅板加工CNC鋁管加工
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC 鋁板加工CNC不銹鋼加工CNC銅板加工CNC鋅板加工CNC鋁管加工
	gague
MOQ	
/mm	+/- 0.01mm
T / T	50T / T; 50
	CNC 鋁板加工CNC不銹鋼加工CNC銅板加工CNC鋅板加工CNC鋁管加工
	CNC 鋁板加工CNC不銹鋼加工CNC銅板加工CNC鋅板加工CNC鋁管加工
	20-25T / T 50
	CNC 鋁板加工
1.Name	OEM CNC 鋁板加工
2.Process	CNC 鋁板加工
3.Material	AL6061 AL6065AL6063AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01mm
6.	100mm
7.Specification	OEM service
8.	2530mm
9.	CNC 鋁板加工accessoried
10.	AustrialEU
11.	ISO 9001
ISO	1. 10mm
2.	
3. sureface	finishmentkindlsavailable
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM