

Inspection Report


Report No.: XYA-140511
Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYA-140511 Item No.XY-142038	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142038	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	0000 0000000000000000 0000000000000000 OEM0000000000000000 0000
000000	000000 ADC12A38000
00	000 00000000
0000	000 000000000000000000000000000000 000000
00000	000 00000000000000000000
0000	CNC 000000000000000000000000 000000000000CNC0000
0000	00 0000000000gague00000000000000000000 000000000000000000000000000000 00 00000000000000000000000000000000000000 00
MOQ	00
00/00	+/- 0.01000000
000	T / T 5050T / T0000000000;00
0000	CNC 0000000000000000CNC000000000000 0000-0000000000000000
00000000	000 000000000000000000000000 0000000000000000000000000000
000	000 00
00	20-25&NBSP000 T / T 50000000
0000	00 00000000
1.Name	00000000OEM0000000000
2.Process	0000000000CNC000000
3.	000000ADC12A38000
4.Surface	0000000000000000nickle00000 00000000
5.Tolerance	000 +/- 0.0100000000000000
6	000000100000
7.Specification	0OEM0000000000000000
8	000000000000000025-3000
9	0000000000000000000000000000 00accessoried00000000
10	0000000000000000AustrialEU00
11&NBSP	00000ISO 9001
000000	
ISO	00000110000000
2	000000000000000000
3	surefacefinishment00kindlsavailable00
	0000000000000040
5	00000000
	0000600000
7	0000000000000000
00000000	
000000000000&NBSP	0000000000000000000000 000
0000000000000000	
0000000000000000	ISO9001
00000000000000000	000000
OEM	0000000000000000