

Inspection Report

Report No.: XYDA-140502
Supplier : XY-GLOBAL

Inspection Date: 1st Jun, 2014
Inspector: Leo

Inspection only for: PO . XYDA-140502 Item No.140589	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140589	14000PCS	1% inspection	0pcs	No failure	14000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Product:

Material	Material: ADC12/A380
Surface	Surface: nickel
Tolerance	Tolerance: +/- 0.01
MOQ	MOQ: 1000
Lead time	Lead time: 20-25 days
Payment	Payment: T/T, 50% advance, 50% before delivery
1.Name	1.Name: OEM
2.Process	2.Process: CNC
3.Material	3.Material: ADC12/A380
4.Surface	4.Surface: nickel
5.Tolerance	5.Tolerance: +/- 0.01
6	6: 1000
7.Specification	7.Specification: OEM service
8	8: 25/30
9	9: accessoried
10	10: Austrial/EU
11	11: ISO 9001
ISO	ISO 1. 10
2	2:
3. sureface	3. sureface: finishment kinds available
4	4:
5	5:
6	6:
7	7:
8	8:
9	9:
10	10: ISO9001
11	11:
OEM	OEM: