

**Inspection Report**

**Report No.:** XYJ-140309  
**Supplier :** XY-GLOBAL

**Inspection Date:** 2<sup>th</sup> Apr, 2014  
**Inspector:** Leo

Inspection only for: PO . XYJ-140309 Item No. 1000832	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1000832	6000PCS	1% inspection	0pcs	No failure	6000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4. Product
	
5. Product:	6. Product:

ชื่อ	ชื่อ บริษัท/ชื่อผลิตภัณฑ์ <b>ชื่อผลิตภัณฑ์</b> ชื่อ บริษัท OEM <b>ชื่อผลิตภัณฑ์</b>
วัสดุ	วัสดุ ADC12/A380
รูป	รูป ผลิตภัณฑ์
ขนาด	ขนาด ผลิตภัณฑ์/ขนาดผลิตภัณฑ์
สี	สี ผลิตภัณฑ์/สีผลิตภัณฑ์
กระบวนการ	CNC <b>CNC</b>
การเคลือบ	การเคลือบ <b>gague</b>
MOQ	MOQ
ความแม่นยำ	+/- 0.01
เวลา	T / T 50/50 T / T
เครื่องจักร	CNC <b>CNC</b>
การรับประกัน	การรับประกัน
ราคา	ราคา
น้ำหนัก	20-25 &nbsp; T / T 50
การบรรจุ	<b>การบรรจุ</b>
1.Name	ชื่อ บริษัท/ชื่อผลิตภัณฑ์ OEM
2.Process	CNC
3.	ADC12/A380
4.Surface	การเคลือบ <b>nickle</b>
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	<b>accessoried</b>
10.	Austrial/EU
11&nbsp;	ISO 9001
1	<b>ISO 10</b>
2.	
3	sureface/finishment kinds/available
	4
5.	
	6
7.	
	&nbsp; T / T 50
	ISO9001
OEM	