

Inspection Report

Report No.: XYL-150729
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150729 Item No. XY11LM029	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM029	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

Company	Company Name: OEM Company
Part	Part Name: ADC12/A380
Material	Material: Aluminum
Process	Process: CNC Machining
Surface	Surface: CNC Machining
MOQ	MOQ: 1000
Tolerance	Tolerance: +/- 0.01mm
Lead Time	Lead Time: 50 days / 50 days
Payment	Payment: CNC Machining
Quality	Quality: CNC Machining
Price	Price: 20-25 T / T 50
MOQ	MOQ: 1000
1.Name	1.Name: OEM Company
2.Process	2.Process: CNC Machining
3.Material	3.Material: ADC12/A380
4.Surface	4.Surface: CNC Machining
5.Tolerance	5.Tolerance: +/- 0.01mm
6.Price	6.Price: 100
7.Specification	7.Specification: OEM service
8	8: 25-30
9	9: accessoried
10	10: Austrial EU
11	11: ISO 9001
1	1: ISO 10
2	2:
3	3: sureface finishment kinds available
4	4:
5	5:
6	6:
7	7:
8	8:
9	9:
10	10: ISO9001
11	11:
12	12: OEM

Safety is our serious job for our worker and engineer team

