

Inspection Report

Report No.: XYL-150725
Supplier: XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO: XYL-150725 Item No. XY11LM025	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM025	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

Part Name	Part Name OEM Part Name
Material	Material ADC12/A380
Surface	Surface
MOQ	MOQ
Tolerance	Tolerance +/- 0.01
Lead Time	Lead Time T / T 50
Process	Process CNC
Accessories	Accessories
1. Name	1. Name OEM
2. Process	2. Process CNC
3. Material	3. Material ADC12/A380
4. Surface	4. Surface
5. Tolerance	5. Tolerance +/- 0.01
6. MOQ	6. MOQ 100
7. Specification	7. Specification OEM service
8. Lead Time	8. Lead Time 25-30
9. Accessories	9. Accessories accessoried
10. Certification	10. Certification Austria EU
11. ISO 9001	11. ISO 9001
12. ISO 10000	12. ISO 10000
13. Surface Finishment	13. Surface Finishment kinds available
14. Lead Time	14. Lead Time
15. MOQ	15. MOQ
16. Process	16. Process
17. Accessories	17. Accessories
18. Certification	18. Certification
19. ISO 9001	19. ISO 9001
20. Lead Time	20. Lead Time
21. OEM	21. OEM

High qualified surface treatment can make your parts perfect !!!

