

Inspection Report


Report No.: XYBA-141119
Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-141119 Item No. XY21ZC038	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC038	5000Set	7% inspection	0pcs	No failure	6000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50T / T;
	CNC CNC CNC CNC
	CNC
	20-25T / T 50
	CNC
1.Name	OEM CNC
2.Process	CNC
3.Material	AL6061 AL6065AL6063AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEMserice
8.	2530
9.	CNC accessoried
10.	AustrialEU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kindlsavailable
	4.
5.	
	6.
7.	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM