

Inspection Report

Report No.: XYSL-150610
Supplier : XY-GLOBAL

Inspection Date: 15th July, 2015
Inspector: Leo

Inspection only for: PO : XYSL-150610 Item No. XY31XL008	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL008	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

pocdmis		4471	450011108	11.06.2015	14.16
Lot		0001	0001	0001	0001
1		0001	0001	0001	0001
2		0001	0001	0001	0001
3		0001	0001	0001	0001
4		0001	0001	0001	0001
5		0001	0001	0001	0001
6		0001	0001	0001	0001
7		0001	0001	0001	0001
8		0001	0001	0001	0001
9		0001	0001	0001	0001
10		0001	0001	0001	0001
11		0001	0001	0001	0001
12		0001	0001	0001	0001
13		0001	0001	0001	0001
14		0001	0001	0001	0001
15		0001	0001	0001	0001
16		0001	0001	0001	0001
17		0001	0001	0001	0001
18		0001	0001	0001	0001
19		0001	0001	0001	0001
20		0001	0001	0001	0001
21		0001	0001	0001	0001
22		0001	0001	0001	0001
23		0001	0001	0001	0001
24		0001	0001	0001	0001
25		0001	0001	0001	0001
26		0001	0001	0001	0001
27		0001	0001	0001	0001
28		0001	0001	0001	0001
29		0001	0001	0001	0001
30		0001	0001	0001	0001
31		0001	0001	0001	0001
32		0001	0001	0001	0001
33		0001	0001	0001	0001
34		0001	0001	0001	0001
35		0001	0001	0001	0001
36		0001	0001	0001	0001
37		0001	0001	0001	0001
38		0001	0001	0001	0001
39		0001	0001	0001	0001
40		0001	0001	0001	0001
41		0001	0001	0001	0001
42		0001	0001	0001	0001
43		0001	0001	0001	0001
44		0001	0001	0001	0001
45		0001	0001	0001	0001
46		0001	0001	0001	0001
47		0001	0001	0001	0001
48		0001	0001	0001	0001
49		0001	0001	0001	0001
50		0001	0001	0001	0001
51		0001	0001	0001	0001
52		0001	0001	0001	0001
53		0001	0001	0001	0001
54		0001	0001	0001	0001
55		0001	0001	0001	0001
56		0001	0001	0001	0001
57		0001	0001	0001	0001
58		0001	0001	0001	0001
59		0001	0001	0001	0001
60		0001	0001	0001	0001
61		0001	0001	0001	0001
62		0001	0001	0001	0001
63		0001	0001	0001	0001
64		0001	0001	0001	0001
65		0001	0001	0001	0001
66		0001	0001	0001	0001
67		0001	0001	0001	0001
68		0001	0001	0001	0001
69		0001	0001	0001	0001
70		0001	0001	0001	0001
71		0001	0001	0001	0001
72		0001	0001	0001	0001
73		0001	0001	0001	0001
74		0001	0001	0001	0001
75		0001	0001	0001	0001
76		0001	0001	0001	0001
77		0001	0001	0001	0001
78		0001	0001	0001	0001
79		0001	0001	0001	0001
80		0001	0001	0001	0001
81		0001	0001	0001	0001
82		0001	0001	0001	0001
83		0001	0001	0001	0001
84		0001	0001	0001	0001
85		0001	0001	0001	0001
86		0001	0001	0001	0001
87		0001	0001	0001	0001
88		0001	0001	0001	0001
89		0001	0001	0001	0001
90		0001	0001	0001	0001
91		0001	0001	0001	0001
92		0001	0001	0001	0001
93		0001	0001	0001	0001
94		0001	0001	0001	0001
95		0001	0001	0001	0001
96		0001	0001	0001	0001
97		0001	0001	0001	0001
98		0001	0001	0001	0001
99		0001	0001	0001	0001
100		0001	0001	0001	0001

6. report

[illegible]

Safety is our serious job for our worker and engineer team

