

Inspection Report


Report No.: XYN-140628
Supplier : XY-GLOBAL

Inspection Date: 19th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140628 Item No.180019	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
180019	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	CNC 零件加工CNC零件加工CNC零件加工CNC零件加工CNC零件加工
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
	CNC 零件加工
	gague
MOQ	
	+/- 0.01mm
	T / T 50%
	CNC 零件加工CNC 零件加工CNC 零件加工CNC 零件加工
	20-25T / T 50%
	CNC 零件加工
1.Name	OEM CNC 零件加工
2.Process	CNC 零件加工
3.	AL6061 AL6065AL6063AL7075POM
4.Surface	nickle
5.Tolerance	+/- 0.01mm
6.	100%
7.Specification	OEM 零件加工
8.	25-30mm
9.	CNC 零件加工accessoried
10.	AustrialEU
11&NBSP	ISO 9001
	ISO 10
2.	
3.sureface	finishmentkindlsabailable
	4.
5.	
	6.
7.	
	&NBSP
	ISO9001
	OEM