

Inspection Report

Report No.: XYL-150726
Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
Inspector: Leo

Inspection only for: PO : XYL-150726 Item No. XY11LM026	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM026	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	OEM
ADC12A380	
CNC	
gague	
MOQ	
+/- 0.01	
T / T 50	
CNC	
2025 T / T 50	
1.Name OEM	
2.Process CNC	
3.Material ADC12A380	
4.Surface	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM serice	
8 25-30	
9 accessoried	
10 Austrial EU	
11.ISO 9001	
1 ISO10	
2	
3 sureface finishment kinds available	
4	
5	
6	
7	
ISO9001	
OEM	

High qualified surface treatment can make your parts perfect !!!

