

Peças de precisão de alumínio

Inspection Report

Report No.: XYA-130814  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Sep-, 2013  
 Inspector: LEO

Inspection only for: PO . XYA-130814    Item No.130353	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130353	1000PCS	3% inspection	0pcs	No failure	1000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Product: