

## Inspection Report

Report No.: XYSL-140618

Supplier : XY-GLOBAL

Inspection Date: 25<sup>th</sup> Jul, 2014

Inspector: Leo

|                                     |                    |
|-------------------------------------|--------------------|
| Inspection only for:                | Inspection Result: |
| PO : XYSL-140618 Item No. XY11WD041 | PASS               |

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY11WD041   | 10000PCS      | 5% inspection | 0pcs         | No failure          | 10000pcs        |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure

### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product

| Item | Spec   | Actual | Unit | Pass/Fail |
|------|--------|--------|------|-----------|
| 1    | 1.0000 | 1.0000 | mm   | Pass      |
| 2    | 1.0000 | 1.0000 | mm   | Pass      |
| 3    | 1.0000 | 1.0000 | mm   | Pass      |
| 4    | 1.0000 | 1.0000 | mm   | Pass      |
| 5    | 1.0000 | 1.0000 | mm   | Pass      |
| 6    | 1.0000 | 1.0000 | mm   | Pass      |
| 7    | 1.0000 | 1.0000 | mm   | Pass      |
| 8    | 1.0000 | 1.0000 | mm   | Pass      |
| 9    | 1.0000 | 1.0000 | mm   | Pass      |
| 10   | 1.0000 | 1.0000 | mm   | Pass      |
| 11   | 1.0000 | 1.0000 | mm   | Pass      |
| 12   | 1.0000 | 1.0000 | mm   | Pass      |
| 13   | 1.0000 | 1.0000 | mm   | Pass      |
| 14   | 1.0000 | 1.0000 | mm   | Pass      |
| 15   | 1.0000 | 1.0000 | mm   | Pass      |
| 16   | 1.0000 | 1.0000 | mm   | Pass      |
| 17   | 1.0000 | 1.0000 | mm   | Pass      |
| 18   | 1.0000 | 1.0000 | mm   | Pass      |
| 19   | 1.0000 | 1.0000 | mm   | Pass      |
| 20   | 1.0000 | 1.0000 | mm   | Pass      |
| 21   | 1.0000 | 1.0000 | mm   | Pass      |
| 22   | 1.0000 | 1.0000 | mm   | Pass      |
| 23   | 1.0000 | 1.0000 | mm   | Pass      |
| 24   | 1.0000 | 1.0000 | mm   | Pass      |
| 25   | 1.0000 | 1.0000 | mm   | Pass      |
| 26   | 1.0000 | 1.0000 | mm   | Pass      |
| 27   | 1.0000 | 1.0000 | mm   | Pass      |
| 28   | 1.0000 | 1.0000 | mm   | Pass      |
| 29   | 1.0000 | 1.0000 | mm   | Pass      |
| 30   | 1.0000 | 1.0000 | mm   | Pass      |
| 31   | 1.0000 | 1.0000 | mm   | Pass      |
| 32   | 1.0000 | 1.0000 | mm   | Pass      |
| 33   | 1.0000 | 1.0000 | mm   | Pass      |
| 34   | 1.0000 | 1.0000 | mm   | Pass      |
| 35   | 1.0000 | 1.0000 | mm   | Pass      |
| 36   | 1.0000 | 1.0000 | mm   | Pass      |
| 37   | 1.0000 | 1.0000 | mm   | Pass      |
| 38   | 1.0000 | 1.0000 | mm   | Pass      |
| 39   | 1.0000 | 1.0000 | mm   | Pass      |
| 40   | 1.0000 | 1.0000 | mm   | Pass      |
| 41   | 1.0000 | 1.0000 | mm   | Pass      |
| 42   | 1.0000 | 1.0000 | mm   | Pass      |
| 43   | 1.0000 | 1.0000 | mm   | Pass      |
| 44   | 1.0000 | 1.0000 | mm   | Pass      |
| 45   | 1.0000 | 1.0000 | mm   | Pass      |
| 46   | 1.0000 | 1.0000 | mm   | Pass      |
| 47   | 1.0000 | 1.0000 | mm   | Pass      |
| 48   | 1.0000 | 1.0000 | mm   | Pass      |
| 49   | 1.0000 | 1.0000 | mm   | Pass      |
| 50   | 1.0000 | 1.0000 | mm   | Pass      |
| 51   | 1.0000 | 1.0000 | mm   | Pass      |
| 52   | 1.0000 | 1.0000 | mm   | Pass      |
| 53   | 1.0000 | 1.0000 | mm   | Pass      |
| 54   | 1.0000 | 1.0000 | mm   | Pass      |
| 55   | 1.0000 | 1.0000 | mm   | Pass      |
| 56   | 1.0000 | 1.0000 | mm   | Pass      |
| 57   | 1.0000 | 1.0000 | mm   | Pass      |
| 58   | 1.0000 | 1.0000 | mm   | Pass      |
| 59   | 1.0000 | 1.0000 | mm   | Pass      |
| 60   | 1.0000 | 1.0000 | mm   | Pass      |
| 61   | 1.0000 | 1.0000 | mm   | Pass      |
| 62   | 1.0000 | 1.0000 | mm   | Pass      |
| 63   | 1.0000 | 1.0000 | mm   | Pass      |
| 64   | 1.0000 | 1.0000 | mm   | Pass      |
| 65   | 1.0000 | 1.0000 | mm   | Pass      |
| 66   | 1.0000 | 1.0000 | mm   | Pass      |
| 67   | 1.0000 | 1.0000 | mm   | Pass      |
| 68   | 1.0000 | 1.0000 | mm   | Pass      |
| 69   | 1.0000 | 1.0000 | mm   | Pass      |
| 70   | 1.0000 | 1.0000 | mm   | Pass      |
| 71   | 1.0000 | 1.0000 | mm   | Pass      |
| 72   | 1.0000 | 1.0000 | mm   | Pass      |
| 73   | 1.0000 | 1.0000 | mm   | Pass      |
| 74   | 1.0000 | 1.0000 | mm   | Pass      |
| 75   | 1.0000 | 1.0000 | mm   | Pass      |
| 76   | 1.0000 | 1.0000 | mm   | Pass      |
| 77   | 1.0000 | 1.0000 | mm   | Pass      |
| 78   | 1.0000 | 1.0000 | mm   | Pass      |
| 79   | 1.0000 | 1.0000 | mm   | Pass      |
| 80   | 1.0000 | 1.0000 | mm   | Pass      |
| 81   | 1.0000 | 1.0000 | mm   | Pass      |
| 82   | 1.0000 | 1.0000 | mm   | Pass      |
| 83   | 1.0000 | 1.0000 | mm   | Pass      |
| 84   | 1.0000 | 1.0000 | mm   | Pass      |
| 85   | 1.0000 | 1.0000 | mm   | Pass      |
| 86   | 1.0000 | 1.0000 | mm   | Pass      |
| 87   | 1.0000 | 1.0000 | mm   | Pass      |
| 88   | 1.0000 | 1.0000 | mm   | Pass      |
| 89   | 1.0000 | 1.0000 | mm   | Pass      |
| 90   | 1.0000 | 1.0000 | mm   | Pass      |
| 91   | 1.0000 | 1.0000 | mm   | Pass      |
| 92   | 1.0000 | 1.0000 | mm   | Pass      |
| 93   | 1.0000 | 1.0000 | mm   | Pass      |
| 94   | 1.0000 | 1.0000 | mm   | Pass      |
| 95   | 1.0000 | 1.0000 | mm   | Pass      |
| 96   | 1.0000 | 1.0000 | mm   | Pass      |
| 97   | 1.0000 | 1.0000 | mm   | Pass      |
| 98   | 1.0000 | 1.0000 | mm   | Pass      |
| 99   | 1.0000 | 1.0000 | mm   | Pass      |
| 100  | 1.0000 | 1.0000 | mm   | Pass      |

6. The test report

[illegible]