

Inspection Report

Report No.: XYLA-150417
Supplier : XY-GLOBAL

Inspection Date: 21th May, 2015
Inspector: Leo

Inspection only for: PO : XYLA-150417 Item No. XY31PC027	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC027	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Pass	Fail	Pass	Fail
1	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
2	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
3	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
4	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
5	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
6	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
7	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
8	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
9	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
10	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
11	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
12	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
13	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
14	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
15	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
16	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
17	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
18	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
19	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
20	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
21	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
22	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
23	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
24	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
25	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
26	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
27	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
28	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
29	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
30	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
31	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
32	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
33	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
34	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
35	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
36	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
37	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
38	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
39	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
40	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
41	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
42	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
43	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
44	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
45	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
46	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
47	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
48	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
49	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
50	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
51	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
52	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
53	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
54	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
55	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
56	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
57	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
58	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
59	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
60	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
61	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
62	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
63	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
64	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
65	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
66	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
67	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
68	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
69	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
70	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
71	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
72	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
73	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
74	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
75	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
76	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
77	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
78	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
79	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
80	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
81	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
82	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
83	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
84	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
85	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
86	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
87	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
88	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
89	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
90	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
91	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
92	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
93	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
94	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
95	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
96	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
97	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
98	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
99	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%
100	1.0000	1.0000	0.0000	100.00%	0.00%	100.00%	0.00%

6. report

[illegible]

High qualified surface treatment can make your parts perfect !!!

