

Inspection Report

Report No.: XYSK-140527
Supplier : XY-GLOBAL

Inspection Date: 28th Jun, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140527 Item No. XY11WD025	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD025	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY11WD025									
NO	Q'ty	100	200	300	400	500	600	700	800
1	100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
2	200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
3	300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
4	400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
5	500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
6	600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
7	700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
8	800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
9	900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
10	1000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
11	1100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
12	1200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
13	1300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
14	1400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
15	1500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
16	1600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
17	1700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
18	1800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
19	1900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
20	2000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
21	2100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
22	2200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
23	2300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
24	2400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
25	2500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
26	2600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
27	2700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
28	2800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
29	2900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
30	3000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
31	3100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
32	3200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
33	3300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
34	3400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
35	3500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
36	3600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
37	3700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
38	3800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
39	3900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
40	4000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
41	4100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
42	4200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
43	4300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
44	4400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
45	4500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
46	4600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
47	4700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
48	4800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
49	4900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
50	5000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
51	5100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
52	5200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
53	5300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
54	5400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
55	5500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
56	5600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
57	5700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
58	5800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
59	5900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
60	6000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
61	6100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
62	6200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
63	6300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
64	6400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
65	6500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
66	6600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
67	6700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
68	6800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
69	6900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
70	7000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
71	7100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
72	7200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
73	7300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
74	7400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
75	7500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
76	7600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
77	7700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
78	7800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
79	7900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
80	8000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
81	8100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
82	8200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
83	8300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
84	8400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
85	8500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
86	8600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
87	8700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
88	8800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
89	8900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
90	9000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
91	9100	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
92	9200	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
93	9300	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
94	9400	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
95	9500	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
96	9600	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
97	9700	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
98	9800	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
99	9900	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
100	10000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000

6. Dimensions report

[illegible]