

0000	
	CNCDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDD
0000	00000000000000000000000000000000000000
MOQ	
00/000	+/- 0.01mm
	<u>000</u> T / T 50 <u>00000000000</u> 50 <u>0</u> T / T <u>00</u> 0
	CNC0000000000CNC0000000000000000000000
	Т / Т 5000000020-2500
1.Name	
2.DDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDD	
3.MaterialADC12_A380_	
4.0000000000000000000000000000000000000	
5.000+/- 0.01mm00000000	
7OEM_serice	
8.00000000000025-3000	
10.0000000000000EU00 11.000ISO 9001	
1 160000	
1. ISO[[]10[][][] 2.[][][][][][][][][][][][][][][][][][][]	
5.NNN	



Customized various shapes



Professional design

CERTICICATE



WELCOME TO OUR COMPANY



CUSTOMER'S FEEDBACK



WELCOME TO OUR COMPANY

Hi Naky,

I have gct the parts.
For T1 injection, the parts looks very good!
I was able make an assembly, it functionsvery well.

I already saw few element which must be fixed.
I will deliver you full report when I will finish the tests-it will take some timesince I have a lot of tests to do.

I would like to thank you and all XY team for the cooperation and the attention.



Hilvy.

Time flies too fast!

Best wishes to all your family and friends.

So sorry for not responding to Naky's email. your projects with us have been great! Our testing has gones well because the parts you gave us were great quality.

Thanks for all your support,

Joel



Dear Naky,

We are very happy with the last shipment. Everything is perfect. We do not have any inquiries currently.

Thanks.





Hi Nancy,

Yes, many thanks for the samples Nancy. The products and quality are really nice. We will keep the products as a reference and present to our clients in the future. Hopefully we can work on some more products types together soon.

Many thanks, Helga



Dear Jack,

I got a feedback of our engineer that metal [arts 12000008 are almost ok but the thread's surface could and should be smoother. The goods really have a good quality but please try to improve the material's surface inside the thread.

Our engineer suggested to change the mixture of your drilling fluid. I hope this could help, so that we can receive "not only" good parts but perfect ones in the future.

Thanks.

