

Inspection Report

Report No.: XYBA-141122

Supplier : XY-GLOBAL


Inspection Date: 19th Dec-, 2014

Inspector:LEO

Inspection only for:	Inspection Result:
PO : XYBA-141122 Item No. XY21ZC040	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC040	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

1. Name: 2. Process: 3. Material: 4. Surface 5. Tolerance: 6. .Quality: 7.Specification: 8. 9. 10. 11.	1. Name: 2. Process: 3. Material: 4. Surface 5. Tolerance: 6. .Quality: 7.Specification: 8. 9. 10. 11.
--	--