



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYF-130806

Supplier : XY-GLOBAL

Inspection Date: 2th Sep, 2013

Inspector: LEO

Inspection only for: PO : XYK-130806 Item No. 200-140097	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-140097	20000Set	100% inspection	0pcs	No failure	20000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

The table is a detailed measurement report for part 200-140097. It includes columns for Item No., Lot No., Date, and various dimensions. The data is organized into sections for different views (Top, Bottom, Side, etc.) and includes specific measurements and tolerances for each dimension.

6. inspection reports

[illegible]